

GARMIN[®]

Navigation Data Alert

DATE: 16 December 2024
CYCLE: 2412 & 2413, Effective 28 NOV 2024 to 22 JAN 2025
SUBJECT: Incorrect Turn Direction on Instrument Approach Procedures at LOWW

DESCRIPTION

Garmin has been made aware that the following procedures were delivered with an incorrect turn direction:

| Airport | Procedures | Error |
|----------------|-------------------|--|
| LOWW | RNP RWY 34 | Incorrect turn direction at waypoint WW975 on the MAB5N and PES5N Transitions. |
| LOWW | ILS or LOC RWY 34 | |
| LOWW | VOR RWY 34 | |

This alert applies to the 2412 & 2413 cycle of the Garmin Navigation Database. This Data Alert does not apply to the Jeppesen NavData database.

PILOT ACTION

Use the approach transitions with extreme caution.

RESOLUTION

These procedures will be corrected in the 2501 cycle of the Garmin Navigation Database.

THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS UTILIZING THE GARMIN NAVIGATION DATABASE

Garmin requests that the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to fly.garmin.com and select "[Aviation Data Error Report](#)."