

GARMIN[®]

Navigation Data Alert

DATE: 6 May 2024

CYCLE: 2404 - Until Further Notice, Effective 18 APR 2024

SUBJECT: Missing Displaced Threshold Lengths

DESCRIPTION

Garmin has been made aware that the following runways were delivered with missing displaced threshold lengths:

Airport	Runway	Country
BIRF	RW05	Iceland
BIVO	RW04/22	Iceland
EBST	RW06/24	Belgium
EBTN	RW06/24	Belgium
EBTN	RW17/35	Belgium
EETI	RW32	Estonia
EFKA	RW17/35	Finland
EGDI	RW34	United Kingdom
EGEC	RW11/29	United Kingdom
EGKA	RW02/20	United Kingdom
EGKA	RW06/24	United Kingdom
EGKB	RW03	United Kingdom
EGNW	RW33	United Kingdom
EGOE	RW22/28	United Kingdom
EGOW	RW08/26	United Kingdom
EGPF	RW23	United Kingdom
EGPO	RW06	United Kingdom
EGSV	RW02	United Kingdom
EGSV	RW07	United Kingdom
EGSY	RW07	United Kingdom
EGUW	RW05	United Kingdom
EGWC	RW06/24	United Kingdom
EGWN	RW02/20	United Kingdom

Airport	Runway	Country
EGWN	RW07/25	United Kingdom
EGXY	RW33	United Kingdom
EGYD	RW02/26	United Kingdom
EGYE	RW06/28	United Kingdom
EHDL	RW19	Netherlands
EHGR	RW02/20	Netherlands
EHGR	RW10/28	Netherlands
EHLW	RW05/23	Netherlands
EHLW	RW09	Netherlands
EHTW	RW05/23	Netherlands
EHVK	RW06L/24R	Netherlands
EHVK	RW06R/24L	Netherlands
EIWT	RW07/25	Ireland
EKBI	RW09/27	Denmark
EKCH	RW12/30	Denmark
EKCH	RW22R	Denmark
EKHG	RW15/33	Denmark
EKRK	RW29	Denmark
EKVH	RW11/29	Denmark
EPGL	RW26L	Poland
EPKA	RW11R/29L	Poland
EPKM	RW05L/23R	Poland
EPML	RW08R	Poland

Airport	Runway	Country
EPPG	RW10L/28R	Poland
EPZE	RW05/23	Poland
ESIB	RW11	Sweden
ESMQ	RW05/23	Sweden
ESSL	RW11	Sweden
ETMN	RW08	Germany
ETSI	RW06L	Germany
LESA	RW03/21	Spain
LFOP	RW05/23	France
LFOQ	RW02L	France
LFOQ	RW02R	France
LFQU	RW08	France
LGKV	RW05/23	Greece
LGNX	RW36	Greece
LICR	RW29	Italy
LIME	RW12	Italy
LPBJ	RW01R/19L	Portugal
LPCR	RW11/29	Portugal
LPCS	RW35	Portugal
LPGR	RW09/27	Portugal
LPMI	RW17/35	Portugal
LPPI	RW27	Portugal

Airport	Runway	Country
LPTN	RW08	Portugal
LSGG	RW04	Switzerland
LSGS	RW07/25	Switzerland
LSMA	RW01	Switzerland
LSMD	RW11/29	Switzerland
LSME	RW04/22	Switzerland
LSMP	RW05/23	Switzerland
LSZA	RW01/19	Switzerland
LSZG	RW06	Switzerland
LSZR	RW10/28	Switzerland
LXGB	RW09/27	Gibraltar
LYSU	RW14/32	Serbia
MKTP	RW14/32	Jamacia
MMAN	RW20	Mexico
MUPB	RW21	Cuba
SCTB	RW19	Chile
SKPD	RW36	Columbia
SLBJ	RW01/19	Bolivia
SPLP	RW02	Peru
TVSM	RW09	St. Vincent

This Data Alert applies to cycle 2404 and until further notice of the Garmin Navigation Database. This Data Alert does not apply to the Jeppesen NavData database.

PILOT ACTION

Pilots should exercise caution when conducting operations involving affected runways.

RESOLUTION

The runways will be corrected in a future cycle of the Garmin Navigation Database.

THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS UTILIZING THE GARMIN NAVIGATION DATABASE

Garmin requests that the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to fly.garmin.com and select "Aviation Data Error Report."