



**JEPPESEN**<sup>®</sup>  
**NavData**<sup>®</sup> Alert

**!! URGENT !!**

**Date:** 04 June 2024

**Subject:** Annecy, France (LFLP)  
Meythet  
Multiple Procedures  
Cycle 2406

*Procedure coding incorrect*

Jeppesen NavData for cycle 2406, effective 13 June 2024, contains incorrect data for Meythet; Annecy, France (LFLP).

Following STARs are affected:

**OMANI 1P [OMAN1P]: do not use,**  
**FEDZI 3P missing from database,**  
**AMVAR 1P [AMVA1P] should read AMVAR 3P,**  
**LTP 1A [LTP1A] should read LTP 3A,**  
**MEBAK 1P [MEBA1P] should read MEBAK 3P,**  
**MURRO 1P [MURO1P] should read MURRO 3P,**  
**PINED 1P [PINE1P] should read PINED 3P,**  
**ROMAM 1P [ROMA1P] should read ROMAM 3P,**  
**SALEV 1P [SALE1P] should read SALEV 3P,**  
**SALEV 1Q [SALE1Q] should read SALEV 3Q.**

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO  
APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

Revised coding will appear in Jeppesen NavData for cycle 2407, effective 11 July 2024. Until then an entry will appear in the NavData Change Notices and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#).

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:  
+1-303-328-4445 (Western Hemisphere)  
+49 610 250 8175 (Eastern Hemisphere)  
E-mail: [navdatasupport@boeing.com](mailto:navdatasupport@boeing.com)

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.