



# JEPPESEN<sup>®</sup>

## NavData<sup>®</sup> Alert

**!! URGENT !!**

**Date:** 11 June 2024

**Subject:** Lorient, France  
Lann-Bihoué (LFRH)  
Multiple Procedures  
Cycle 2406

***Procedure coding incorrect***

Jeppesen NavData for cycle 2406, effective 13 June 2024, contains incorrect data for Lann-Bihoué; Lorient, France (LFRH).

Following STARs are affected:

- ARE 1L [ARE1L], BAGAD 1L [BAGA1L], ARE 2N [ARE2N], ARE 1M [ARE1M] **do not use.**
- ERCOZ 2N, ERCOZ 1M **missing from database.**

Following SIDs are affected:

- ARE 1E [ARE1E], ARE 1S [ARE1S], ARE 1W [ARE1W], BAGAD 1E [BAGA1E], LENSU 1W [LENS1W]: **do not use.**

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

Revised coding will appear in Jeppesen NavData for cycle 2407, effective 11 July 2024. Until then an entry will appear in the NavData Change Notices and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#).

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:  
+1-303-328-4445 (Western Hemisphere)  
+49 610 250 8175 (Eastern Hemisphere)  
E-mail: [navdatasupport@boeing.com](mailto:navdatasupport@boeing.com)

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.