

FliteCharts Data Alert

TO: Users of all Garmin aviation products using the Australia or South Pacific FliteCharts® database
DATE: August 6, 2024
CYCLE: 2408
SUBJECT: GOLD COAST AIRPORT (YBCG) RWY 32 TEMPORARY INSTRUMENT APPROACH PROCEDURES

DESCRIPTION

Airservices Australia has advised Garmin that temporary approach procedures for RWY 32 at Gold Coast (YBCG), Queensland, Australia have been published in SUP H90/24, effective August 8, 2024. The Pacific Airshow will be held between 15-18 August and requires temporary amended approach procedures to avoid TRA R930A and R930B. The following charts are not included in the Australia or South Pacific FliteCharts database:

- RNP T RWY 32
- RNP R RWY 32 (AR)
- RNP S RWY 32 (AR)

The original AIP supplement can be seen at the following link:

<https://www.airservicesaustralia.com/aip/current/sup/s24-h90.pdf>

PILOT ACTION

Be aware the RNP T RWY 32, RNP R RWY 32 (AR), and RNP S RWY 32 (AR) approach charts are unavailable at Gold Coast (YBCG), Queensland, Australia in Australia or South Pacific FliteCharts for cycle 2408.

Alerts are written for the currently effective cycle and next cycle. It is possible that data from prior cycles is also affected. Garmin recommends using the latest effective data cycle.

RESOLUTION

SUP H90/24 self-cancels at 202408180900 UTC.

THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS USING THE AUSTRALIA OR SOUTH PACIFIC FLITECHARTS DATABASE

Garmin requests that the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to fly.garmin.com and select "[Aviation Data Error Report](#)."