



JEPPESEN[®]

NavData[®] Alert

!! URGENT !!

Date: 25 October 2024

Subject: Benson, United Kingdom
Benson (EGUB)
Multiple procedures
Cycle 2411

Procedure information outdated

Jeppesen NavData for cycle 2411, effective 31 October 2024, contains incorrect data for Benson, United Kingdom (EGUB). UK MIL AIP AMDT 011-24 AIRAC (eff 31 OCT 24) was received after the ICAO specified date for aeronautical information publication.

Copter TACAN RWY 01 and **Copter TACAN RWY 19** should not be used.
TACAN RWY 01 and **TACAN RWY 19** are missing from database.
ILS DME RWY 19 distance for holding FF19 (inbound course 009°) should read 2.2 NM.
TACAN BSO coordinates should read N 51° 37' 16.8" W 001° 05' 53.4"

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised coding will appear in Jeppesen NavData for cycle 2412, effective 28 November 2024. Until then an entry will appear in the NavData Change Notices, and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#).

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Support Portal: support.jeppesen.com
E-mail: navdatasupport@boeing.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.