

!! URGENT !!

Date: 20 December 2024

Subject: Villacoublay, France Velizy (LFPV) Multiple procedures Cycle 2413

Procedure information outdated

Jeppesen NavData for cycle 2413, effective 26 December 2024, contains incorrect data for Villacoublay; Velizy, France (LFPV). FRANCE MIL AMDT 001-25 (MIAC 2) (eff 26 DEC 24) was received after the ICAO specified date for aeronautical information publication.

SID RWY 09 procedures EVX 1A [EVX1A] and EVX 1B [EVX1B] should read ELCOB 2A [ELCP2A] and ELCOB 2B [ELCO2B].

SID RWY 09 procedures EVX 1P [EVX1P] and EVX 1V [EVX1V] should not be used.

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised coding will appear in Jeppesen NavData for cycle 2501, effective 23 January 2025. Until then an entry will appear in the NavData Change Notices and this Alert will be posted on the Jeppesen Web site: <u>Notices and Alerts</u>.

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at: Support Portal: support Portal: support.jeppesen.com E-mail: navdatasupport@boeing.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.