

GARMIN[®]

Navigation Data Alert

DATE: 16 December 2024
CYCLE: 2412 & 2413, Effective 28 NOV 2024 to 22 JAN 2025
SUBJECT: Incorrect Turn Direction on Instrument Approach Procedures at EHAM

DESCRIPTION

Garmin has been made aware that the following procedures were delivered with an incorrect turn direction:

Airport	Procedure	Error
EHAM	ILS or LOC RWY 18C	Incorrect turn direction at waypoint NIRSI on the RIV1H approach transition.

This Data Alert applies to the 2412 & 2413 cycle of the Garmin Navigation Database. This Data Alert does not apply to the Jeppesen NavData database.

PILOT ACTION

Use the approach transition with extreme caution.

RESOLUTION

The procedures will be corrected in the 2501 cycle of the Garmin Navigation Database.

THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS UTILIZING THE GARMIN NAVIGATION DATABASE

Garmin requests that the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to fly.garmin.com and select "[Aviation Data Error Report](#)."