

DATE: 09 January 2025

CYCLE: 2413 & 2501 Effective 26 DEC 2024 to 19 FEB 2025

SUBJECT: Incorrect Missed Approach Point

DESCRIPTION

Garmin has been made aware that the following procedure was delivered with an incorrect missed approach point:

Airport	Procedure	Error
KMCC	VOR/DME RWY 34	The missed approach point for this procedure is at
	(D34)	MCC 1.4 DME, not runway 34.

This Data Alert applies to the 2413 & 2501 cycle of the Garmin Navigation Database. This Data Alert does not apply to the Jeppesen NavData database.

PILOT ACTION

Use the procedure with extreme caution

RESOLUTION

The procedure will be corrected in the 2502 cycle of the Garmin Navigation Database.

THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS UTILIZING THE GARMIN NAVIGATION DATABASE

Garmin requests that the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to fly.garmin.com and select "Aviation Data Error Report."