

!! URGENT !!

Date: 21 June 2024

Subject: Jacksonville, Arkansas Little Rock AFB (KLRF) ILS or LOC Rwy 25 Cycle 2406

Incorrect Localizer Ident

Jeppesen NavData for cycle 2406, effective 13 June 2024, contains an incorrect runway 25 localizer ident.

The runway 25 localizer ident should be ITYV.

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised coding will appear in Jeppesen NavData for cycle 2407, effective 11 July 2024. Until then an entry will appear in the NavData Change Notices, and this Alert will be posted on the Jeppesen Web site: <u>Notices and Alerts</u>.

Please refer to the Little Rock AFB; Jacksonville, Arkansas (KLRF) ILS or LOC Rwy 25 chart dated 12 APR 24, effective 18 April, for valid information.

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at: +1-303-328-4445 (Western Hemisphere) +49 610 250 8175 (Eastern Hemisphere) E-mail: navdatasupport@boeing.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.