

!! URGENT !!

Date: 9 July 2024

Subject: Nakatsu, Japan

Tsuiki (RJFZ) Tacan Rwy 07 Cycle 2407

Procedure coding outdated

Jeppesen NavData for cycle 2407, effective 11 July 2024, contains incorrect data for Nakatsu; Tsuiki, Japan (RJFZ).

Tacan Rwy 07 - waypoint UPGUN should read ENLUG, waypoint VABLA should read IPDIM.

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised coding will appear in Jeppesen NavData for cycle 2408, effective 08 August 2024. Until then an entry will appear in the NavData Change Notices and this Alert will be posted on the Jeppesen Web site: Notices and Alerts.

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

+1-303-328-4445 (Western Hemisphere) +49 610 250 8175 (Eastern Hemisphere)

E-mail: navdatasupport@boeing.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.